
==== Shimadzu LabSolutions UV Spectrum ====

EDUV2.lcd




==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\Branco 1.lcd

Acquired by	: System Administrator
Sample Name	: Branco 1
Sample ID	: Branco 1
Tray#	: 1
Vail #	: 1
Injection Volume	: 10 uL
Data File Name	: Branco 1.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: PCIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 13:52:09
Data Processed	: 26/06/2018 13:56:10

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\Branco 1.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 1.lcd

Acquired by	: System Administrator
Sample Name	: PCIN 1
Sample ID	: PCIN 1
Tray#	: 1
Vail #	: 2
Injection Volume	: 10 uL
Data File Name	: PCIN 1.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: PCIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 13:55:44
Data Processed	: 26/06/2018 14:06:28

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 1.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA

Name	Area
Cafeina	773216


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 2.lcd

Acquired by	: System Administrator
Sample Name	: PCIN 2
Sample ID	: PCIN 2
Tray#	: 1
Vail #	: 2
Injection Volume	: 10 uL
Data File Name	: PCIN 2.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: PCIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 13:59:21
Data Processed	: 26/06/2018 14:06:41

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 2.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA

Name	Area
Cafeina	771953


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 3.lcd

Acquired by	: System Administrator
Sample Name	: PCIN 3
Sample ID	: PCIN 3
Tray#	: 1
Vail #	: 2
Injection Volume	: 10 uL
Data File Name	: PCIN 3.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: PCIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 14:02:57
Data Processed	: 26/06/2018 14:06:54

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 3.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA


Name	Area
Cafeina	773574

==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\Branco 2.lcd

Acquired by	: System Administrator
Sample Name	: Branco 2
Sample ID	: Branco 2
Tray#	: 1
Vail #	: 1
Injection Volume	: 10 uL
Data File Name	: Branco 2.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: PCIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 14:06:32
Data Processed	: 26/06/2018 14:21:09

<Chromatogram>



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 4.lcd

Acquired by	: System Administrator
Sample Name	: PCIN 4
Sample ID	: PCIN 4
Tray#	: 1
Vail #	: 2
Injection Volume	: 10 uL
Data File Name	: PCIN 4.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: PCIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 14:10:06
Data Processed	: 26/06/2018 14:22:12

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 4.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA

Name	Area
Cafeina	777978


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 5.lcd

Acquired by	: System Administrator
Sample Name	: PCIN 5
Sample ID	: PCIN 5
Tray#	: 1
Vail #	: 2
Injection Volume	: 10 uL
Data File Name	: PCIN 5.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: PCIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 14:13:40
Data Processed	: 26/06/2018 14:22:26

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 5.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA

Name	Area
Cafeina	774390


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 6.lcd

Acquired by	: System Administrator
Sample Name	: PCIN 6
Sample ID	: PCIN 6
Tray#	: 1
Vail #	: 2
Injection Volume	: 10 uL
Data File Name	: PCIN 6.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: PCIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 14:17:15
Data Processed	: 26/06/2018 14:22:57

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\PCIN 6.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA

Name	Area
Cafeina	777348


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\Branco 3.lcd

Acquired by	: System Administrator
Sample Name	: Branco 3
Sample ID	: Branco 3
Tray#	: 1
Vail #	: 1
Injection Volume	: 10 uL
Data File Name	: Branco 3.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: PCIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 14:20:49
Data Processed	: 26/06/2018 14:24:13

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\Branco 3.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\LDUV 1.lcd

Acquired by	: System Administrator
Sample Name	: LDUV 1
Sample ID	: LDUV 1
Tray#	: 1
Vail #	: 1
Injection Volume	: 10 uL
Data File Name	: LDUV 1.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: LDUV.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 14:27:09
Data Processed	: 26/06/2018 14:34:47

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\LDUV 1.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results


PDA

==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\LDUV 2.lcd

Acquired by	: System Administrator
Sample Name	: LDUV 2
Sample ID	: LDUV 2
Tray#	: 1
Vail #	: 2
Injection Volume	: 10 uL
Data File Name	: LDUV 2.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: LDUV.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 14:30:44
Data Processed	: 26/06/2018 14:45:52

<Chromatogram>



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA


Name	Area
Cafeina	256314

==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\LDUV 3.lcd

Acquired by	: System Administrator
Sample Name	: LDUV 3
Sample ID	: LDUV 3
Tray#	: 1
Vail #	: 3
Injection Volume	: 10 uL
Data File Name	: LDUV 3.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: LDUV.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 14:34:19
Data Processed	: 26/06/2018 14:46:04

<Chromatogram>



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA

Name	Area
Cafeina	511833


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\LDUV 4.lcd

Acquired by	: System Administrator
Sample Name	: LDUV 4
Sample ID	: LDUV 4
Tray#	: 1
Vail #	: 4
Injection Volume	: 10 uL
Data File Name	: LDUV 4.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: LDUV.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 14:37:54
Data Processed	: 26/06/2018 14:51:43

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\LDUV 4.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA


Name	Area
Cafeina	759191

==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\LDUV 5.lcd

Acquired by	: System Administrator
Sample Name	: LDUV 5
Sample ID	: LDUV 5
Tray#	: 1
Vail #	: 5
Injection Volume	: 10 uL
Data File Name	: LDUV 5.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: LDUV.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 14:41:28
Data Processed	: 26/06/2018 14:51:57

<Chromatogram>



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA

Name	Area
Cafeina	979581


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\LIIN 1.lcd

Acquired by	: System Administrator
Sample Name	: LIIN 1
Sample ID	: LIIN 1
Tray#	: 1
Vail #	: 1
Injection Volume	: 0,1 uL
Data File Name	: LIIN 1.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: LIIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 15:26:02
Data Processed	: 26/06/2018 15:45:11

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\LIIN 1.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\LIIN 2.lcd

Acquired by	: System Administrator
Sample Name	: LIIN 2
Sample ID	: LIIN 2
Tray#	: 1
Vail #	: 1
Injection Volume	: 5 uL
Data File Name	: LIIN 2.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: LIIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 15:29:36
Data Processed	: 26/06/2018 15:45:32

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\LIIN 2.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA


Name	Area
Cafeina	408979

==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\LIIN 3.lcd

Acquired by	: System Administrator
Sample Name	: LIIN 3
Sample ID	: LIIN 3
Tray#	: 1
Vail #	: 1
Injection Volume	: 10 uL
Data File Name	: LIIN 3.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: LIIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 15:33:12
Data Processed	: 26/06/2018 15:46:02

<Chromatogram>



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA

Name	Area
Cafeina	799752


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\LIIN 4.lcd

Acquired by	: System Administrator
Sample Name	: LIIN 4
Sample ID	: LIIN 4
Tray#	: 1
Vail #	: 1
Injection Volume	: 15 uL
Data File Name	: LIIN 4.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: LIIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 15:36:48
Data Processed	: 26/06/2018 15:46:19

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\LIIN 4.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA

Name	Area
Cafeina	1209350


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\LIIN 5.lcd

Acquired by	: System Administrator
Sample Name	: LIIN 5
Sample ID	: LIIN 5
Tray#	: 1
Vail #	: 1
Injection Volume	: 20 uL
Data File Name	: LIIN 5.lcd
Method File Name	: Qualificação.lcm
Batch File Name	: LIIN.lcb
Report File Name	: DEFAULT.lsr
Data Acquired	: 26/06/2018 15:40:24
Data Processed	: 26/06/2018 15:46:30

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\LIIN 5.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA

Name	Area
Cafeina	1591341


==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\Grad AB1.lcd

Acquired by	: System Administrator
Sample Name	: Grad AB
Sample ID	: Grad AB
Tray#	: 1
Vail #	: 1
Injection Volume	: 0,1 uL
Data File Name	: Grad AB1.lcd
Method File Name	: Grad AB.lcm
Batch File Name	:
Report File Name	: DEFAULT.lsr
Data Acquired	: 27/06/2018 08:41:45
Data Processed	: 27/06/2018 09:02:32

<Chromatogram>

C:\LabSolutions\Data\CBM-20A\Qualificação\Grad AB1.lcd



1 PDA Multi 1/273nm,4nm

Quantitative Results


PDA

==== Shimadzu LCsolution Analysis Report ====

C:\LabSolutions\Data\CBM-20A\Qualificação\Grad AC1.lcd

Acquired by	: System Administrator
Sample Name	: Grad AC
Sample ID	: Grad AC
Tray#	: 1
Vail #	: 1
Injection Volume	: 0,1 uL
Data File Name	: Grad AC1.lcd
Method File Name	: Grad AC.lcm
Batch File Name	:
Report File Name	: DEFAULT.lsr
Data Acquired	: 27/06/2018 09:04:16
Data Processed	: 27/06/2018 09:23:46

<Chromatogram>



1 PDA Multi 1/273nm,4nm

Quantitative Results

PDA